

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
1938 Journey to Europe and Germany in a VA	Safety Fast	October	2021	18
1938 Motor Show SVW Cars	SVW Review	Issue 9	2000	16
1997 SVW Weekend - Pembury, Kent	SVW Review	Issue 7	1998	8
2002 SVW Weekend - Westphalia, Germany	SVW Review	Issue 12	2003	18
2003 SVW Weekend - Kent	SVW Review	Issue 13	2004	13
2004 SVW Weekend - Rhenen, Holland	SVW Review	Issue 14	2005	15
2005 SVW Weekend - Norfolk	SVW Review	Issue 15	2006	14
2006 SVW Weekend - Dorset	SVW Review	Issue 16	2007	15
2007 SVW Weekend - Ironbridge	SVW Review	Issue 17	2008	17
2008 SVW Weekend - Naarden, Holland	SVW Review	Issue 18	2009	19
2009 SVW Weekend - Cambridge	SVW Review	Issue 19	2010	19
2010 Peking to Paris Rally	SVW Review	Issue 19	2010	31
2010 Peking to Paris Rally	SVW Review	Issue 20	2011	4
2010 SVW Weekend - Munchengladback, Germany	SVW Review	Issue 20	2011	23
2011 SVW Weekend - Isle of White	SVW Review	Issue 21	2012	23
2012 SVW Weekend - Yorkshire	SVW Review	Issue 22	2013	23
2013 Peking to Paris Rally	SVW Review	Issue 23	2014	40
2013 SVW Weekend - Beuzeville, France	SVW Review	Issue 23	2014	23
2014 SVW Weekend - Oxfordshire	SVW Review	Issue 24	2015	23
2015 SVW Weekend - Chichester	Safety Fast	September	2015	43
2015 SVW Weekend - Chichester	SVW Review	Issue 25	2016	23
2016 SVW Event - Ardennes Belgium	Safety Fast	September	2016	38
2016 SVW Weekend - Ardennes Belgium	SVW Review	Issue 26	2017	25
2017 SVW Event - Colchester	SVW Review	Issue 27	2018	29
2018 SVW Event - Cotswolds & Bristol	SVW Review	Issue 28	2019	27
2019 Register Event - Alphen aan de Rijn, Holland	SVW Review	Issue 29	2020	29
2019 SVW Register Award Winners	SVW Review	Issue 29	2020	23
2019 SVW Register Event - Alphen aan de Rijn	Safety Fast	September	2019	36
2021 SVW Event - Battle, East Sussex	Safety Fast	September	2021	45
2021 SVW Register Award Winners	SVW Review	Issue 31	2022	21
2021 SVW Register Event - Lincolnshire	SVW Review	Issue 32	2023	25
2022 SVW Event - Battle, East Sussex	SVW Review	Issue 31	2022	23
2022 SVW Event - Lincolnshire	Safety Fast	September	2022	50
2022 SVW Register Award Winners	SVW Review	Issue 32	2023	23
2023 - SVW Event - York	Safety Fast	September	2023	48
2023 Pre 56 MG Rally - Newbies in New Zealand	SVW Review	Issue 32	2023	9
2023 Pre 56 MG Rally - Touring in New Zealand	SVW Review	Issue 32	2023	5
2023 SVW Register Award Winners	SVW Review	Issue 33	2024	22
2023 SVW Register Event - Yorkshire	SVW Review	Issue 33	2024	25
2024 Award Winners	SVW Review	Issue 34	2025	29
2024 Pre 56 New Zealand Rally	SVW Review	Issue 34	2025	30
2024 SVW Event Netherlands Report	SVW Review	Issue 34	2025	24
2024 SVW Register Event - Holland	Safety Fast	September	2024	56
2025 SVW Register Event - Yorkshire	Safety Fast	September	2025	44
50th Anniversary SVW Register	SVW Review	Issue 26	2017	4
60th Anniversary VA 0773T Gordon Vogthur	Safety Fast	June	1998	42
64 Years with a VA Geoff Wilson - AHS 87	MG Enthusiast	November	2015	50
680 UYG - WA Keller Replica	MG Enthusiast	Spring	2019	52
70th Birthdays	SVW Review	Issue 18	2009	26
A Tale of three SA's in Australia	SVW Review	Issue 27	2018	35
ABL 999	SVW Review	Issue 6	1997	51
Acceleration Figures taken on Marcham Straight SA	MG Technical Information	06 January 1936		
Aesthetic Design in Motor Cars - Cecil Kimber	SVW Review	Issue 24	2015	38
African Safari SA Harry Hickling	MG Enthusiast	January	2012	50
AHS 87 - 64 Years with a VA Geoff Wilson	MG Enthusiast	November	2015	50
AHS 87 - VA Tourer	MG Enthusiast	October	1995	51
Air Cleaner element replacement (In mini tips)	SVW Review	Issue 21	2012	17
Air Crash wrecks an SVW	SVW Review	Issue 27	2018	19
Air Filter Colour	Safety Fast	May	1994	44
Air Intake Manifold (holes in bottom)	Safety Fast	January	2020	81
Air Manifold	Safety Fast	May	1969	18
Airy SA Coupe (Australia Special Body)	Safety Fast	September	2003	15
Airy SA Coupe History (Australia Special Body)	MG Enthusiast	April	2012	72
Alan Dakeyne - Obituary.	Safety Fast	August	2023	78
Alette Horns	Safety Fast	June	1992	22
Alternator replacement for a Dynamo	SVW Review	Issue 30	2021	45
AMO 602 - VA Saloon Road Test	MG Enthusiast	June	2008	42
Anti Freeze - Modern formulations (V8 Reg)	Safety Fast	April	2010	50
Anti Theft Protection	Safety Fast	April	1995	11
Approved Extras 1939	SVW Review	March	1978	28
Approved Extras 1939 SA	SVW Review	Issue 6	1997	45
Art Deco and SVW's	SVW Review	Issue 24	2015	4
Art Deco in New Zealand 2024	SVW Review	Issue 33	2024	5
Art Deco Motor Show - 2024 Napier New Zealand	SVW Review	Issue 34	2025	45
Art Deco Weekend - Napier, New Zealand, 2015	SVW Review	Issue 24	2015	7

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
Australian Members Update	SVW Review	Issue 29	2020	45
AUT 732	SVW Review	Issue 34	2025	16
AUT 732 In Memory of George West	SVW Review	Issue 29	2020	13
Axel Beams and Steering Arms Heat Treatment	MG Service Information Sheet	December	1933	10
Axle Ratios	SVW Review	Issue 12	2003	4
Back Axel Ratios SA	SVW Review	Issue 34	2025	53
Back Axle (SA) Oil leak from Nosepiece	Safety Fast	January	1991	21
Badge Bar change SA	MG Technical Information	05 November 1936		SA 0903
Balance Pipe Restrictor - Rapid Tick over	Safety Fast	April	2015	83
Bangers and Cash programme - SA 2678 & 2859	SVW Review	Issue 31	2022	19
Bangers and Cash SA's	Safety Fast	March	2022	48
BAP 689 VA Tourer	MG Enthusiast	April	2021	28
Bas de Voogd - Obituary	Safety Fast	September	2019	34
Bas de Voogd - Tribute	SVW Review	Issue 29	2020	7
Bathurst 2015	SVW Review	Issue 25	2016	7
Bathurst 2015	Safety Fast	March	2016	41
Battery	Safety Fast	January	1994	38
Battery Conditioner	Safety Fast	April	2015	15
Battery Disconnect Switch	Safety Fast	November	1991	8
Battery Main Lead re-routed SA	MG Technical Information	05 January 1938		SA 2013
Battery Sulphating	Safety Fast	May	1993	45
Battery/Floorboards	Safety Fast	April	1982	25
BBL 333 VA Saloon History	SVW Review	Issue 18	2009	17
Bearings - Clearance Markings	SVW Bulletin	December	1968	15
Bearings - Front Hub	Safety Fast	July	1969	18
Bearings - Main & Big end	Safety Fast	May	1989	29
Bearings - Rear Hub (T Type)	Safety Fast	August	1992	27
Bearings used on VA	SVW Newsletter	February	1980	n/a
Berlin and Back 1995	Safety Fast	March	1995	44
Bill Wallis with VA MG 5630	Safety Fast	May	1997	20
Bio Fuels	Safety Fast	March	2011	40
Biofuel - Petrol	Safety Fast	January	2012	23
BJB 617	Safety Fast	May	2000	13
Blast Cleaning	MG Enthusiast	March	2012	68
BMH Heritage Certificate	MG Enthusiast	December	2022	70
BMJ 13 VA Tourer (Mick Greaves)	MG Enthusiast	December	1998	62
BMO 759 - Goodbye Ladybird	SVW Review	Issue 26	2017	29
BMO 759 - How not to buy an SVW part 1	SVW Review	Issue 18	2009	28
BMO 759 - How not to buy an SVW part 2	SVW Review	Issue 20	2011	32
BMO 759 How not to buy an SVW (part 3)	SVW Review	Issue 21	2012	40
BMO 759 How not to buy an SVW (part 4)	SVW Review	Issue 22	2013	40
BMO 759 the continuing story (part 5)	SVW Review	Issue 23	2014	37
BMW 770	Safety Fast	October	1997	23
BMW 770	SVW Review	Issue 31	2022	13
BMW 770 - Front Cover of Safety Fast	Safety Fast	July	2015	Front
BMW 770 (Black Beauties)	MG Enthusiast	March	2017	62
BMW 770 at Buckingham Palace	SVW Review	Issue 26	2017	22
Bodies - Special	Safety Fast	June	1983	31
Body Louvers change to open forward (from body No. 740/3795) SA	MG Technical Information	30 November 1936		
Body Styles	Safety Fast	January	1980	18
Bonnet Buffers (from body 591/5851) VA	MG Technical Information	01 February 1938		
Bonnet fitted with louvers in place of doors SA	MG Technical Information	05 January 1938		SA 1980
Bonnet Louvers change (from body No. 923/3932) SA	MG Technical Information	30 November 1936		
Book - Making of SVW Cars	SVW Review	Issue 34	2025	36
BPN 185	Safety Fast	March	2015	40
Brake Adjustment VA	SVW Review	Issue 27	2018	24
Brake Bleeding	SVW Review	Issue 12	2003	23
Brake Bleeding	Safety Fast	March	2009	39
Brake Cable Adjusting Nut change VA	MG Technical Information	07 March 1938		VA 1328
Brake Cables	MG Service Information Sheet	March	1938	37
Brake Cables SA	MG Service Information Sheet	January	1937	40
Brake Drums	Safety Fast	March	2009	39
Brake Fluid	SVW Review	Issue 23	2014	8
Brake Fluid - DOT 5	Safety Fast	November	1999	29
Brake Fluid - Silicon	Safety Fast	March	1982	12
Brake Fluid - Silicon	Safety Fast	October	1982	12
Brake Fluid - Silicon	Safety Fast	January	1983	29
Brake Fluid Leakage	SVW Review	Issue 12	2003	21
Brake Fluid- Types DOT 3, DOT 4, DOT 5.	Safety Fast	March	2009	60
Brake light switch	SVW Review	Issue 16	2007	27
Brake Linings fitting to brake shoes	MG Enthusiast	March	2017	84
Brake Pedal Draft Excluder change VA	MG Technical Information	28 June 1937		
Brake Pipe Line Lockheed SA	MG Service Information Sheet	August	1936	39
Brake Pipe Lines	Safety Fast	May	1991	36
Brake Reservoir	Safety Fast	December	1993	47

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
Brake Shoe Linings Cleaning	SVW Review	Issue 30	2021	17
Brake Shoes	SVW Review	Issue 12	2003	22
Brake Shoes	Safety Fast	March	2009	39
Brake Shoes getting them back on	Safety Fast	March	2004	18
Brakes	Safety Fast	January	1990	24
Brakes - Pulling to one side	Safety Fast	September	2012	38
Brakes - Total System	SVW Bulletin	December	1968	9
Brakes - VA	Safety Fast	October	1993	43
Brakes Detailed Overall	SVW Review	Issue 6	1997	58
Brakes Drum	Safety Fast	August	2018	17
Brakes modifying VA to two leading shoes	SVW Review	Issue 22	2013	44
Brakes Rear - Oil Leaking Into	Safety Fast	January	1991	21
Braking Efficiency	Safety Fast	September	2009	38
Braking Performance	SVW Review	Issue 11	2002	23
Braking Problem	Safety Fast	September	2018	42
Broken Studs Extraction (MGA)	Safety Fast	July	2018	37
Brooklin Models of VA & SA	Safety Fast	September	2011	41
Bulbs - Legality of LED bulbs	MG Enthusiast	June	2018	74
Bullet Connectors and Faston Connectors	Safety Fast	September	2015	18
Bumper Damping	Safety Fast	December	2011	83
Buying and Selling on Line	MG Enthusiast	August	2012	60
BWS 534	Safety Fast	April	2019	82
Camshaft New Low Lift fitted VA	MG Technical Information	25 May 1939		TPBG 2566
Camshaft Oil Deflector Plate now fitted SA	MG Technical Information	06 May 1938		QPHG 2839
Camshaft Oil Deflector Plate now fitted VA	MG Technical Information	06 May 1938		TPBG 1798
Camshafts	SVW Review	Issue 22	2013	9
Canned Fuel	Safety Fast	March	2007	10
Car Radio	SVW Review	Issue 33	2024	17
Car Security	Safety Fast	September	1996	14
Carburation SU Carburettor	Safety Fast	January	2018	31
Carburettor bowl repair	Safety Fast	December	2015	38
Carburettor Jet and Throttle changes VA	MG Technical Information	17 February 1938		VA 1048
Carburettor Jet connecting rod change VA	MG Technical Information	17 February 1938		VA 0950
Carburettor Jet Control change SA	MG Technical Information	17 February 1938		SA 2258
Carburettor Oil	Safety Fast	April	1993	25
Carburettor Overhaul	Safety Fast	May	1992	19
Carburettor Repair (Twin Cam)	Safety Fast	December	2020	49
Carburettor Tuning and Balancing	MG Enthusiast	January	2009	70
Carburettors	Safety Fast	August	1993	56
Carburettors	Safety Fast	February	2020	80
Carburetors and Exhausts	Safety Fast	March	1999	29
Carburetors SU	Safety Fast	December	2002	11
Carburetors SU	Safety Fast	May	2002	32
Castor Angle wedges	SVW Review	Issue 23	2014	8
CBL 192 - the Kimber Kollektief Netherlands	SVW Review	Issue 32	2023	39
CBL 192 - VA2437	SVW Review	Issue 31	2022	35
CBP 631 SA with a Dickey Seat	SVW Review	Issue 34	2025	5
CDF 779 VA 0923 Barn Find	SVW Review	Issue 34	2025	9
CDU 188 SA Saloon restoration	MG Enthusiast	June	2001	20
Cecil Kimber (of no fixed abode/)	SVW Review	Issue 25	2016	33
Centre lock Wheels	Safety Fast	January	1992	15
Changing the Engine Oil	Safety Fast	May	2021	31
Charlesworth Bodies	Safety Fast	March	2021	46
Charlesworth rebuild Part 1	SVW Review	December	1976	7
Charlesworth rebuild Part 2	SVW Review	March	1978	11
Charlesworth rebuild Part 3	SVW Review	March	1980	7
Charlesworth Tourers - SA	SVW Review	Issue 9	2000	5
Chassis	Safety Fast	March	1984	34
Chassis (VA)	Safety Fast	January	1991	20
Chassis and Body Shell Identification Numbers	Safety Fast	March	2010	40
Chassis Dimensions Drawing VA	MG Service Information Sheet	July	1938	55
Chassis Frame (New) SA	MG Technical Information	13 February 1939		SA 2752
Chassis Number location	Safety Fast	March	2008	36
Chassis numbers	Safety Fast	May	1982	13
Chassis numbers VA	SVW Review	Issue 6	1997	49
Checks to make if engine will not start	Safety Fast	November	2000	47
Children in Cars	Safety Fast	February	2010	80
Children in Cars	SVW Review	Issue 19	2010	34
Choke Cable repair (Magnetite)	Safety Fast	July	2022	55
Chronometric Instruments	SVW Review	Issue 34	2025	11
Chrstie SA 2337	SVW Review	Issue 27	2018	39
Classic Car Crime	Safety Fast	November	2000	15
Classic Vehicle Insurance	Safety Fast	November	2015	16
Clutch - Cork or Kevlar	SVW Review	Issue 29	2020	20
Clutch - Oil leaking onto	Safety Fast	December	1991	53

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
Clutch replacement SA	SVW Review	Issue 21	2012	4
Clutch/Gearbox	Safety Fast	June	1980	19
Clutches	Safety Fast	March	1987	32
Coach built Bodies	SVW Review	Issue 29	2020	17
Colour Chart	SVW Review	March	1978	26
Colours	Safety Fast	October	1968	9
Colours	SVW Review	March	1978	8
Colours	Safety Fast	May	1979	18
Colours	Safety Fast	October	1984	27
Colours	Safety Fast	December	1988	36
Colours - Engine, Gearbox, Bulkhead	Safety Fast	May	1979	18
Colours Modern Equivalents	SVW Review	Issue 6	1997	45
Colours SA	SVW Review	Issue 6	1997	44
Competition Cars	Safety Fast	February	1983	31
Competition SA & VA's	MG Enthusiast	March	1998	70
Conrods, Bearings, and Lubrication	SVW Review	Issue 19	2010	23
Converting to Negative Earth	MG Enthusiast	March	2012	74
Cooling system	Safety Fast	June	1969	15
Cooling system problems	Safety Fast	March	2006	9
Cooling the Carburettors	Safety Fast	September	2000	20
Core Plugs	Safety Fast	August	1985	35
Core Plugs	Safety Fast	July	1985	33
Core Plugs	Safety Fast	June	1989	37
Core Plugs - How to make them (MMM)	Safety Fast	October	2010	45
Core Plugs - Neil Cairns	Safety Fast	January	2015	39
Core Plugs (MGB)	MG Enthusiast	February	2018	70
Cracked Axle Hubs	SVW Review	Issue 23	2014	8
Crankshaft and Cylinder Block new VA	MG Technical Information	13 February 1939		TPBG 1891
Crankshaft and Main Bearings (New) SA	MG Technical Information	11 April 1938		QPHG 2715
Crankshaft fitting	MG Enthusiast	June	1992	54
Crankshaft New Damper Weight SA	MG Technical Information	05 January 1938		QPHG 2029
Crankshaft Oil Duct Plugs	MG Service Information Sheet	June	1934	16
Crankshaft Pulley (new) WA	MG Technical Information	25 May 1939		QPJG 752
Crankshaft rear bearing seal (XPAG Engines)	Safety Fast	December	2009	24
Crown wheel and Pinion Changing	SVW Review	Issue 14	2005	4
CTE 737 SA Saloon (Peter Pimm)	MG Enthusiast	February	1999	64
CTF 192 Police Car Pictures	Safety Fast	November	2004	38
CTU 807 - SA 0656	SVW Review	Issue 32	2023	51
CTU 807 - SA Saloon	MG Enthusiast	March	2007	38
CVB 850 VA Tourer Restored	MG Enthusiast	March	2009	40
CXY 851	Safety Fast	March	2022	45
CYE 499 - SA Saloon	MG Enthusiast	September	1995	44
Cylinder block repairs (Y Type)	Safety Fast	June	2006	15
Cylinder Head Overall	SVW Review	Issue 12	2003	12
Cylinder Head Repair (MGA Twin Cam)	Safety Fast	April	2019	49
Cylinder wear and Pre War Piston Design	Safety Fast	March	2000	15
Dashboard	Safety Fast	June	1980	19
Dashboard and Foot ramp change SA	MG Technical Information	05 January 1936		
Dashboard Finish	Safety Fast	May	1994	44
Dashboards - SVW's	SVW Review	Issue 22	2013	30
Data Sheet SVW cars Quick Check-Over	SVW Review	Issue 30	2021	26
Data Sheet VA	SVW Review	Issue 6	1997	66
David Washbourne Award	SVW Review	Issue 28	2019	23
Decoke	Safety Fast	February	2004	13
Defence of the VA	Safety Fast	June	1977	7
DFY 34 - Heirloom One Families Ownership	SVW Review	Issue 30	2021	7
DHU 546 Raymond Griffiths	SVW Review	Issue 25	2016	13
Dipper Switch bracket changed VA	MG Technical Information	05 January 1938		VA 0793
Direction Indicators	Safety Fast	April	1980	15
Display Engine at Kimber House - VA	SVW Review	Issue 24	2015	27
Distributord	Safety Fast	January	2011	56
Distributor - Bob Weights	MG Enthusiast	January	2012	63
Distributor Overhaul	MG Enthusiast	December	2010	62
DJO 804 - A2Prototype VA	MG Enthusiast	Summer	2021	34
DKW 506 - VA1279	SVW Review	Issue 31	2022	49
DLVA Issues when Registering your Car	Safety Fast	February	2023	60
Door Catches - additional catch	Safety Fast	December	2009	83
Door Hinges	Safety Fast	September	2025	47
Drilling out spot welds	Safety Fast	November	1992	41
Drop Dead Gorgeous - VA Tickford MG 6069	MG Enthusiast	January	2015	54
Drum Brakes	Safety Fast	August	2018	17
DTU 999 - VA Tickford	MG Enthusiast	January	2010	48
Dual Fuel Pump SA	MG Service Information Sheet	June	1936	35
Dutch Members Update	SVW Review	Issue 29	2020	37
DWK 685	Safety Fast	March	2022	46

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
DWK 685 Factory prepared Rally VA	SVW Review	Issue 31	2022	7
DXC 688 - SVW's in Films - DXC 688, FYF 92	Safety Fast	March	2018	49
DXC 981 (Jack Wilms)	MG Enthusiast	February	1999	63
Dynamo replacement with a Alternator	SVW Review	Issue 30	2021	45
E10 Petrol	Safety Fast	April	2021	10
EBY 810 - SA Saloon	SVW Review	Issue 30	2021	34
Effects of Ethanol Petrol	Safety Fast	November	2021	65
EHY 214 - VA Saloon	MG Enthusiast	November	2006	34
EKC 777	SVW Review	Issue 31	2022	19
Electric Fan - Advantages	Safety Fast	November	2011	83
Electroplating	SVW Review	Issue 21	2012	12
ELL 148	Safety Fast	March	2003	15
ELM 800 - Memories of a VA Saloon	SVW Review	Issue 24	2015	13
EMS 745 SA Restoration	MG Enthusiast	December	2010	32
END 92	Safety Fast	October	2025	82
End of the Tax Disc	Safety Fast	October	2014	10
Engine - SA	Safety Fast	May	1987	22
Engine Ancestry	SVW Review	March	1980	16
Engine Changed to Dry Clutch. Crankshaft, Filter, Starter. VA	MG Technical Information	07 March 1938		VA 1254
Engine Control Straps	Safety Fast	August	1969	13
Engine Cooling (based on a Morris Ten)	Safety Fast	July	2012	30
Engine Mounting Adjustment VA	MG Service Information Sheet	August	1937	49
Engine Mountings	Safety Fast	June	1969	14
Engine Nuts and Bolts (see also October)	Safety Fast	September	2020	44
Engine Oil	Safety Fast	April	1992	23
Engine Oil	Safety Fast	June	1993	18
Engine Oil.	Safety Fast	June	2023	58
Engine Oils	SVW Review	Issue 20	2011	46
Engine Overall part 1	MG Enthusiast	July	1992	54
Engine Overall part 2	MG Enthusiast	August	1992	35
Engine Overall part 3	MG Enthusiast	September	1992	54
Engine Overall part 4	MG Enthusiast	October	1992	46
Engine Overhaul	SVW Bulletin	June	1970	7
Engine Overheating	SVW Review	Issue 17	2008	22
Engine Performance (Modification Air Cleaner Manifold) VA	MG Service Information Sheet	October	1938	66
Engine Rebuild - VA Police Specification	SVW Review	Issue 20	2011	12
Engine Rebuild SA	SVW Bulletin	June	1970	22
Engine Rebuild SA 2983	SVW Review	Issue 22	2013	4
Engine rebuild VA 1385	SVW Review	Issue 27	2018	45
Engine removal - VA	SVW Review	Issue 20	2011	35
Engine Removal (In mini tips)	SVW Review	Issue 21	2012	17
Engine Removal VA	Safety Fast	September	1982	31
Engine shield rubber change VA	MG Technical Information	05 January 1938		
Engine Testing	Safety Fast	February	1994	26
Engine, Gearbox, Bulkhead Colours	Safety Fast	May	1979	18
Engineering Keys	Safety Fast	January	1995	24
Engineering Keys	Safety Fast	March	1995	25
Engines - Wolseley/Morris/MG	SVW Bulletin	December	1968	8
EWJ 393 - VA Tourer - Fred Clarke	SVW Review	Issue 26	2017	41
Exhaust Flange Sealing	Safety Fast	March	2023	48
Exhaust Manifolds	Safety Fast	January	1980	18
Export VA	Safety Fast	February	1977	14
Extras - Factory approved 1939	SVW Review	March	1978	28
EXX 100 - SA Tickford	Safety Fast	March	2019	44
Facia Panel Replaced SA	MG Technical Information	05 January 1938		
Factory Optional Spares list	SVW Review	Issue 11	2002	10
Factory Photographs	Safety Fast	April	2000	20
Factory prepared Rally VA - DWK 685	SVW Review	Issue 31	2022	7
Factory Production Changes	SVW Review	Issue 25	2016	37
Factory Record Book VA	Safety Fast	March	2008	37
Factory VA Demonstrators	SVW Review	Issue 12	2003	10
Fan Belt Adjustment SA	MG Service Information Sheet	September	1938	63
Filming for Bangers and Cash (SA Saloon)	Safety Fast	March	2021	47
Finding TDC and adjusting Ignition Timing	Safety Fast	September	2001	15
Fire Extinguishers (MGB)	Safety Fast	June	1989	33
First 22 Members of the SVW Register	SVW Newsletter	October	1967	n/a
Fitting Running Board strips	Safety Fast	March	2007	11
Fitting seat Belts to a SA	Safety Fast	September	2009	38
Flasher Installation (Y Type)	Safety Fast	September	1993	29
Floorboards/Battery	Safety Fast	April	1982	25
FLT 565 VA 2269 Discovery	Safety Fast	March	2025	42
FOE 524 - Front Cover of Safety Fast	Safety Fast	May	1986	Front
FOE 524 - Front Cover of Safety Fast	Safety Fast	January	2010	Front
FOE 524 - Kimber Birthday Run	MG Enthusiast	June/July	1989	45
FOE 524 - WA 0550	SVW Review	Issue 22	2013	16

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
Folding a Tickford Hood	Safety Fast	September	2024	59
Foot Brake Adjustment	SVW Review	Issue 12	2003	23
Foot Brake Adjustment	Safety Fast	March	2009	39
Foot Pedal Modification for Big Feet - VA	SVW Review	Issue 28	2019	38
Foot well, Floorboards, and Carpet change. VA	MG Technical Information	05 January 1938		VA 0802
Frances Adam 1917 - 2009	SVW Review	Issue 19	2010	5
Frances Adam Award	Safety Fast	December	1987	31
Frances Adam Award	Safety Fast	November	1993	36
Frances Adam Award	Safety Fast	April	1994	46
Frances Adam Award	Safety Fast	March	2008	36
Frances Adam Award	SVW Review	Issue 28	2019	21
Front Axle and King pin new arrangement SA	MG Technical Information	13 February 1939		SA 2752
Front Axle King Pin Holes	SVW Review	Issue 23	2014	8
Front Axle New (track rod at rear) Also on SA 2074 to SA 2102 SA	MG Technical Information	05 January 1938		SA 2147
Front Axle Overhaul	Safety Fast	March	2008	39
Front Axle Torque cables	Safety Fast	May	1969	18
Front Axle, King Pin, Brake Drum change VA	MG Technical Information	07 March 1938		VA 1254
Front Bumper - replacement mountings	Safety Fast	March	1999	42
Front Bumper change SA	MG Technical Information	05 November 1936		SA 0905
Front Bumper change SA	MG Technical Information	01 May 1937		SA 1501
Front Bumper change SA	MG Technical Information	05 January 1938		SA 1972
Front Bumpers	Safety Fast	March	2020	50
Front Hub Bearings	Safety Fast	July	1969	18
Front Hub change of Oil Seal SA	MG Technical Information	20 June 1936		
Front Hub Replacement - VA	SVW Review	Issue 33	2024	13
Front Spring and Shackle plates change VA	MG Technical Information	07 March 1938		VA 1255
Front Spring Buffers	Safety Fast	March	2019	45
Front Suspension Bump Rubbers	Safety Fast	October	2019	80
Front Wheel Alignment	SVW Review	Issue 11	2002	21
Front Wheel Alignment	Safety Fast	March	2009	37
Front Wheel Toe In	MG Service Information Sheet	February	1948	64
Fuel Filling problems	SVW Review	Issue 32	2023	41
Fuel vaporisation	Safety Fast	November	2011	83
FYF 92 - SVW's in Films - DXC 688, FYF 92	Safety Fast	March	2018	49
Gary Wall Collection	Safety Fast	January	2003	57
Gaskets	SVW Review	Issue 30	2021	19
Gear Box - Jumping out of Gear	Safety Fast	December	2000	29
Gear Box - Nuffield & BMC	Safety Fast	February	2014	22
Gear Box and Propeller shaft change SA	MG Technical Information	20 August 1936		SA 0840
Gear Box Remote Control change SA	MG Technical Information	25 May 1936		SA 0448
Gearbox	Safety Fast	October	1980	8
Gearbox	Safety Fast	July	1981	12
Gearbox Interchangeable Parts	SVW Review	Issue 11	2002	27
Gearbox Main shaft and rear cover change WA	MG Technical Information	25 May 1939		WA 0496
Gearbox Rebuild VA	SVW Review	March	1978	19
Gearbox Removal (SA)	SVW Newsletter	August	1983	n/a
Gearbox Removal (SA)	Safety Fast	January	1991	19
Gearbox Wolseley/MG	Safety Fast	January	1981	22
Gearbox/Clutch	Safety Fast	June	1980	19
Gearboxes	Safety Fast	October	1969	21
Gearboxes	Safety Fast	March	1987	31
Gearboxes	Safety Fast	May	1987	22
Gearboxes	Safety Fast	September	2006	8
General Maintenance	Safety Fast	February	1995	45
Geoffrey Wilson - Obituary	Safety Fast	October	2023	80
German Members Update	SVW Review	Issue 29	2020	39
German Rally (Colin Pratt)	Safety Fast	March	1994	14
German Rally (David Washbourne)	Safety Fast	November	1994	34
Goodwood Revival - 2014, Paul Campbell	SVW Review	Issue 24	2015	10
Gordon Vogtherr Obituary	SVW Review	Issue 33	2024	37
GPU 793 Purchase of SA Saloon	SVW Review	Issue 30	2021	31
Grease Gun change and mounting SA	MG Technical Information	01 February 1938		
Grease Gun change VA	MG Technical Information	01 February 1938		
Grease Nipple change SA	MG Technical Information	13 February 1939		SA 2752
Grease Nipples and Lubrication	Safety Fast	December	1999	15
Grease Nipples changed VA	MG Technical Information	13 February 1939		VA 1795
Greymouth, New Zealand, MG Rally 2015	SVW Review	Issue 24	2015	29
Guide to buying a Classic MG part 1	Safety Fast	September	2009	26
Guide to buying a Classic MG part 2	Safety Fast	October	2009	44
Guide to buying a Classic MG part 3	Safety Fast	November	2009	62
Guide to buying a Classic MG part 4	Safety Fast	December	2009	62
Halfshafts / Hubs	Safety Fast	June	1969	15
Hand Brake Adjustment	SVW Review	Issue 12	2003	23
Hand Brake Cable change SA	MG Technical Information	01 March 1937		SA 1407
Hand Brake Return Spring added SA	MG Technical Information	04 November 1936		SA 0903

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
Hand Brake Return Spring change SA	MG Technical Information	28 May 1937		SA 1798
Hand cranking the Engine	Safety Fast	February	2003	32
Handbrake change SA	MG Technical Information	25 March 1936		SA 0344
Handbrake Failure	SVW Review	Issue 25	2016	44
Hazard Lights (MGB)	Safety Fast	July	1984	27
Headlamp change VA	MG Technical Information	25 May 1939		
Headlights LED conversion	Safety Fast	January	2016	83
Headlights LED conversion (2)	Safety Fast	May	2016	83
Headlining Replacement - VA	SVW Newsletter	Annual	1971/72	4
Heat Treatment of Axel Beams and Steering Arms	MG Service Information Sheet	December	1933	10
Heidelberg via Geneva in a VA - late 1930's	SVW Review	Issue 22	2013	28
Heirloom One Families Ownership SA 2002	SVW Review	Issue 30	2021	7
Hermann Poppensieker (Obituary)	SVW Review	Issue 21	2012	29
History of SA's	SVW Review	Issue 6	1997	40
History of the SVW Range	SVW Review	Issue 28	2019	17
History SVW Register	SVW Review	Issue 25	2016	4
Hoods	Safety Fast	January	1980	18
Horn (from under bonnet to badge bar) VA	MG Technical Information	05 January 1938		VA 0748
Horn reduced to one only SA	MG Technical Information	25 May 1939		SA 2851
Horns - Alette	Safety Fast	June	1992	22
How Many SVW's ?	SVW Review	Issue 23	2014	19
How Not To Buy a VA	SVW Review	Issue 34	2025	40
How not to buy an SVW - BMO 759 (part 3)	SVW Review	Issue 21	2012	40
How not to buy an SVW - BMO 759 (part 4)	SVW Review	Issue 22	2013	40
How not to buy an SVW - BMO 759 part 1	SVW Review	Issue 18	2009	28
How not to buy an SVW - BMO 759 part 2	SVW Review	Issue 20	2011	32
HPK 720 SA Saloon	MG Enthusiast	March	2000	18
Hub Fitting to Rear Drive Shafts	MG Service Information Sheet	June	1934	15
Hub Spine wear	SVW Review	Issue 16	2007	29
Hubs / Halfshafts	Safety Fast	June	1969	15
Ignition Problems	SVW Review	Issue 30	2021	29
Ignition system (T Reg)	Safety Fast	July	2009	60
Ignition Timing and Valve clearances VA	SVW Newsletter	December	1967	2
Ignition Timing setting	Safety Fast	November	2007	81
Ignition Timing setting and finding TDC	Safety Fast	September	2001	15
Importing a Classic Car	Safety Fast	April	2010	36
Importing a Classic Car to the USA Part 1	Safety Fast	August	2023	64
Improved Ventilation SA	MG Service Information Sheet	October	1937	51
In Search of Hens Teeth (Locating a VA)	Safety Fast	November	1994	34
Information File	Safety Fast	May	1991	34
Information from the DVLA	Safety Fast	April	2017	52
Instrument Panel - Finish	Safety Fast	February	2000	47
Instrument Panel - Plating	SVW Newsletter	February	1983	n/a
Insurance / Accident Experience - David Washbourne	SVW Review	Issue 22	2013	7
Insurance Regulatory Updates	Safety Fast	April	2017	16
Insurance Salvage Rights	Safety Fast	November	2012	68
International weekend in Berlin	SVW Review	Issue 6	1997	31
Jackal System	Safety Fast	September	1999	29
Jackall System - Description	SVW Review	Issue 10	2001	24
Jackall System - Rebuild	SVW Review	Issue 32	2023	31
Jackall System change of pipework fittings SA	MG Technical Information	13 February 1939		SA 2752
Jackall Tank Colour	Safety Fast	May	1994	44
Jacks	Safety Fast	June	1981	10
Jacks - Flexible Coupling	Safety Fast	May	1980	18
Jacks - Pump (Difference Early and Late)	Safety Fast	December	1982	32
Jacks - Pump Drawing	Safety Fast	June	1983	20
Jacks (release valve)	Safety Fast	February	1981	15
Jaeger / Smiths Instruments	Safety Fast	March	2019	45
JB 9119 - SA 0304	SVW Review	Issue 34	2025	45
JEV 11	Safety Fast	November	2025	83
Journey (1938) to Europe and Germany in a VA	Safety Fast	October	2021	18
Jubilee Clips	Safety Fast	March	2012	23
Keeping Cool with a SA	SVW Review	Issue 6	1997	29
Keith Bush Tribute	SVW Review	Issue 31	2022	5
Keller Bodied Car	SVW Review	Issue 6	1997	47
Keller Bodies	Safety Fast	October	1981	24
Kimber's 1936 SA Run	SVW Review	Issue 14	2005	20
Kimber's VA CBL 192	Safety Fast	June	1997	23
King Pin Holes re-bushing	SVW Review	Issue 23	2014	8
King Pin Replacement - VA	SVW Review	Issue 28	2019	11
King Pin Thrust arrangement change VA	MG Technical Information	01 February 1938		
King Pins Lubrication VA	MG Service Information Sheet	Assume	1938	59
Lead Free Petrol (Part 1)	Safety Fast	February	2000	29
Lead Free Petrol (Part 2)	Safety Fast	March	2000	29
Lead Free Petrol (Part 3)	Safety Fast	April	2000	29

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
Lead Loading Body Filling	MG Enthusiast	November	2007	68
Leaded Petrol - Additives	MG Enthusiast	January	2000	21
Leaf Springs	SVW Review	Issue 23	2014	8
Leather Care	Safety Fast	September	1994	32
LED Bulbs	Safety Fast	June	2017	84
LED Bulbs (V8)	Safety Fast	August	2017	46
LED Bulbs Legality	MG Enthusiast	June	2018	74
LED Headlights	Safety Fast	January	2016	83
LED Headlights (2)	Safety Fast	May	2016	83
LED Headlights (Magnetite)	Safety Fast	June	2016	44
LED Light Conversions (MG V8)	Safety Fast	April	2014	46
LED Lighting	SVW Review	Issue 24	2015	34
LED Lighting - Pros and Cons	SVW Review	Issue 24	2015	36
LED Tail Lights	SVW Review	Issue 31	2022	51
Lights	Safety Fast	December	1971	6
Lights	Safety Fast	September	2000	15
Lights	Safety Fast	April	2017	38
Lord Nuffield's SA 1879	SVW Review	Issue 27	2018	43
Low oil Pressure	Safety Fast	September	2014	41
Lucas Part Numbers SA	SVW Review	Issue 6	1997	55
Lucas Part Numbers SV	SVW Review	Issue 10	2001	20
Luvac Shock Absorbers	SVW Review	Issue 32	2023	53
Luvax Shock Absorbers	Safety Fast	December	1974	19
Luvax Shock Absorbers	SVW Review	Issue 9	2000	27
Main & Big End Bearings	Safety Fast	May	1989	29
Main Bearings - Red Brass	SVW Review	Issue 33	2024	34
Maintaining Wire Wheels	Safety Fast	March	2001	27
Maintenance Tips - Rocking and Rolling	Safety Fast	March	2009	37
Me and my VA - John Venables	Safety Fast	August	2011	56
Memories of a VA Saloon (ELM 800)	SVW Review	Issue 24	2015	13
Metric bolts fitted to SVW's	MG Enthusiast	July	1991	23
MG 4768 SA Saloon (David Washbourne)	MG Enthusiast	November	2004	38
MG 5026	SVW Review	Issue 16	2007	24
MG 5435 - SA 1944	Safety Fast	July	2023	29
MG 6069 Drop Dead Gorgeous - VA Tickford	MG Enthusiast	January	2015	54
MG 7068 - WA 0394	SVW Review	Issue 32	2023	19
MG Car Company Chassis Files	Safety Fast	November	2003	12
MG Centenary ?	SVW Review	Issue 29	2020	49
MG Rally Greymouth, New Zealand, 2015	SVW Review	Issue 24	2015	29
MG Salesman's Manual	Safety Fast	September	2012	40
Mille Miglia 1937	SVW Review	Issue 14	2005	23
Mille Miglia 1937 Crash. Tommy Wisdom in BRM 70	SVW Review	Issue 23	2014	14
Miss Fuelling	Safety Fast	May	2021	63
Model of a VA	Safety Fast	March	2013	39
Model SVW's from Lansdown Models	MG Enthusiast	September	2020	46
Models of VA & SA (Brooklin)	Safety Fast	September	2011	41
Modern Fuel Problems - Manchester Tests Fuel Part 1	Safety Fast	June	2018	28
Modern Fuel Problems - Manchester Tests Fuel Part 2.1	Safety Fast	October	2018	19
Modern Fuel Problems - Manchester Tests Part 1	Safety Fast	February	2018	38
Modern Fuel Problems - Manchester Tests Part 2	Safety Fast	March	2018	40
Modern Petrol - Manchester Tests (1)	Safety Fast	February	2017	24
Modern Petrol Volatility- Manchester Tests (2)	Safety Fast	March	2017	27
Modern Petrol Volatility- Manchester Tests (3)	Safety Fast	June	2017	16
Morris Morsels - Wet Clutch History	SVW Review	Issue 32	2023	20
MOT Regulations	Safety Fast	December	1992	26
MOT Testing Vehicles of Historical Interest	Safety Fast	June	2018	10
Negative Earth Conversion	MG Enthusiast	March	2012	74
New Pistons SA	MG Technical Information	04 November 1936		QPHG 1166
New Springs - VA	SVW Review	Issue 32	2023	13
New Wheels (change in spoke angle) VA	MG Technical Information	05 January 1938		VA 0740
New Zealand Members Update	SVW Review	Issue 29	2020	41
New Zealand Pre 56 Rally - 2019	SVW Review	Issue 28	2019	7
Newbies in New Zealand - Pre 56 MG Rally 2023	SVW Review	Issue 32	2023	9
News from Down under 2014	SVW Review	Issue 23	2014	34
News from Down under 2018	SVW Review	Issue 27	2018	6
News from Down Under 2024	SVW Review	Issue 34	2025	42
Notes on a the VA Engine	SVW Review	Issue 9	2000	18
Number of SVW's	SVW Review	Issue 23	2014	19
Nuts & Bolts	Safety Fast	April	1995	35
Nuts and Bolts used on SVW Engines (see also October)	Safety Fast	September	2020	44
Oil - Carburettor	Safety Fast	April	1993	25
Oil - Engine	Safety Fast	April	1992	23
Oil - Engine	Safety Fast	June	1993	18
Oil (Classic Oils)	Safety Fast	February	2017	35
Oil Cooler Problems - WA	SVW Review	Issue 10	2001	7

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
Oil Filter Conversion	SVW Review	Issue 21	2012	44
Oil Filter Conversion	Safety Fast	March	2012	43
Oil Filters	Safety Fast	September	1999	15
Oil Gauge Pipe change SA	MG Technical Information	11 April 1938		SA 2428
Oil Gauge Pipe improvement SA	MG Technical Information	17 February 1938		
Oil Gauge Pipe VA	MG Technical Information	11 April 1938		VA 1392
Oil Leak Engine Rear seal (XPAG Engines)	Safety Fast	December	2009	24
Oil Leak to Clutch	Safety Fast	December	1991	53
Oil leak to rear Brakes	Safety Fast	January	1991	21
Oil Leakage - Rocker Cover	Safety Fast	November	2019	80
Oil Leaking from Rear Axel Nosepiece SA	MG Service Information Sheet	August	1938	57
Oil Leaking into Clutch VA	MG Service Information Sheet	September	1938	56
Oil Leaks (XPAG Engine)	Safety Fast	December	2025	76
Oil pick up problem VA	SVW Review	Issue 27	2018	23
Oil Pressure	SVW Review	December	1976	13
Oil pressure	SVW Review	March	1980	18
Oil Pressure	Safety Fast	May	1984	19
Oil Pressure	Safety Fast	March	1995	42
Oil pressure - Low	Safety Fast	September	2014	41
Oil Pressure (T Type)	Safety Fast	January	2001	21
Oil Pressure (VA)	Safety Fast	January	1991	19
Oil Pressure and the Rocker Assembly	Safety Fast	March	2015	20
Oil pressure Relief Valve VA	SVW Review	Issue 27	2018	49
Oil Pumps	Safety Fast	December	1996	26
Oil Seals	Safety Fast	July	1970	16
Oiling System - Tecalamit	SVW Bulletin	December	1968	9
One family owned SA - DFY 34	MG Enthusiast	September	2014	36
Optional Extras - Salesman's Manual	Safety Fast	September	2012	40
Original and Restored cars Comparison SA	SVW Review	Issue 32	2023	37
Originality	SVW Review	Issue 12	2003	8
Overdrive Installation into a WA	SVW Review	Issue 11	2002	9
Overheating	Safety Fast	March	2011	38
Overheating	SVW Review	Issue 13	2004	10
Overheating (TA)	Safety Fast	December	1992	42
Overheating (TA)	SVW Review	Issue 12	2003	14
Owning a VA Tourer	Safety Fast	March	2007	8
Paint Equivalents	SVW Review	March	1978	27
Panel Light Rheostat	Safety Fast	April	1980	15
Paris to Biarritz in a SA	SVW Review	Issue 29	2020	9
Parts Wolseley/MG	Safety Fast	September	1980	8
Pass Lamp reduced to One and fitted in centre SA	MG Technical Information	04 November 1936		SA 0903
Pass Lamps	MG Service Information Sheet	October	1948	78
Peking to Paris 2007 - Part 1	Safety Fast	September	2007	22
Peking to Paris 2007 - Part 2	Safety Fast	October	2007	22
Peking to Paris 2007 - Part 3	Safety Fast	November	2007	67
Peking to Paris 2013 in a SA	Safety Fast	September	2013	20
Peking to Paris 2013 rally	SVW Review	Issue 23	2014	40
Peking to Paris Rally SA Harry Hickling	MG Enthusiast	February	2011	52
Period Tax Discs	Safety Fast	November	2017	81
Peter Ratcliffe Cup	Safety Fast	March	2008	36
Peter Ratcliffe Cup	SVW Review	Issue 28	2019	22
Petrol	Safety Fast	April	1994	24
Petrol - Biofuel	Safety Fast	January	2012	23
Petrol - Effects of Ethanol Petrol	Safety Fast	November	2021	65
Petrol - Manchester Tests (1)	Safety Fast	February	2017	24
Petrol - Manchester XPAG Tests	Safety Fast	February	2019	30
Petrol and Water Pumps	Safety Fast	August	1996	24
Petrol Cap change SA	MG Technical Information	04 November 1936		SA 0903
Petrol Pipe connector repositioned VA	MG Technical Information	25 June 1937		VA 0636
Petrol Pump ( SU )	Safety Fast	May	1994	28
Petrol Pump ( SU )	Safety Fast	July	2007	64
Petrol Spillage elimination when filling	SVW Review	Issue 17	2008	21
Petrol Unleaded	Safety Fast	January	1990	23
Petrol Unleaded	Safety Fast	April	1997	39
Petrol Unleaded	Safety Fast	January	1999	9
Petrol Unleaded (FWD)	Safety Fast	October	1998	31
Petrol Unleaded / Leaded	Safety Fast	July	1996	17
Petrol Unleaded / Leaded	Safety Fast	June	1996	18
Petrol Unleaded Use (MGB)	Safety Fast	April	1994	41
Petrol Volatility- Manchester Tests (2)	Safety Fast	March	2017	27
Petrol Volatility- Manchester Tests (3)	Safety Fast	June	2017	16
Petrol Winter & Summer Grades	Safety Fast	February	1994	17
Piston Rings (Fitting)	MG Service Information Sheet	June	1934	17
Pistons - VA Specialloid	Safety Fast	October	1986	27
Pistons & Bearings - WA	Safety Fast	February	1986	22

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
Pistons BHB (Test Purpose TPBG 2186 to 2285 only) VA	MG Technical Information	13 February 1939		
Pistons Wellworthy (Test Purpose TPBG 2292 to 2391 only) VA	MG Technical Information	13 February 1939		
Plating - Instrument Panel	SVW Newsletter	February	1983	n/a
Police Car CTF 192 Pictures	Safety Fast	November	2004	38
Police Car History VA 1737T	SVW Review	Issue 14	2005	10
Police Cars	Safety Fast	February	1979	21
Police Cars	Safety Fast	July	1984	33
Police Cars	Safety Fast	June	1984	31
Police Cars - Update	SVW Review	Issue 19	2010	26
Police Cars - VA	Safety Fast	April	1981	13
Police Cars - VA	Safety Fast	July	1988	34
Police Cars - VA	Safety Fast	October	1988	24
Police Cars - VA	SVW Review	Issue 11	2002	11
Police Speedometers - VA	Safety Fast	February	2024	81
Police VA Tourers - More details revealed.	SVW Review	Issue 26	2017	49
Pre 56 2024 New Zealand Rally	SVW Review	Issue 34	2025	30
Pre 56 Rally - Geraldine New Zealand	Safety Fast	June	TBA	68
Pre 56 Rally - Taupo New Zealand 2013	SVW Review	Issue 22	2013	36
Pre war Publicly Photographs	MG Enthusiast	June	1991	32
Prince Philip Tribute - (MG Heritage event 2009)	SVW Review	Issue 30	2021	5
Production Changes	SVW Review	Issue 25	2016	37
Production Changes in SA	SVW Review	March	1978	16
Production Information	MG Service Information Sheet	February	1948	32
Prop shaft Replacing UJ's	MG Enthusiast	September	2007	67
Propeller Shaft change WA	MG Technical Information	25 May 1939		WA 0495
Propeller Shaft End Flanges SA	MG Service Information Sheet	June	1936	33
Propeller Shafts	MG Service Information Sheet	June	1934	14
Prototype Developments	SVW Review	Issue 13	2004	4
Prototype VA	Safety Fast	June	1994	33
Prototype VA - DJO 804	MG Enthusiast	Summer	2021	34
Punctures	Safety Fast	July	2003	12
Push Rods (+2mm longer) VA	MG Technical Information	25 May 1939		TPBG 2731
Push Rods and Timing Chain Replacements	SVW Review	Issue 29	2020	36
Questionnaire	Safety Fast	November	1990	38
Racing VA	Safety Fast	October	1988	34
Radiator Slats	SVW Bulletin	June	1970	3
Radios - Masteradio	SVW Review	Issue 15	2006	26
Rapid Tick over - Balance Pipe Restrictor	Safety Fast	April	2015	83
Ratcliffe Cup Winners 2001 to 2019	SVW Review	Issue 30	2021	23
RC 5411 VA Restoration	MG Enthusiast	March	2018	46
Rear Axel Bevel Pinion Housing change (from axle No. 1609) VA	MG Technical Information	11 April 1938		
Rear Axel Filler Plug Spanner SA	MG Service Information Sheet	April	1937	47
Rear Axle and Rear Spring change VA	MG Technical Information	07 March 1938		VA 1255
Rear Axle Ratios	Safety Fast	June	2008	80
Rear Axles for MG's	Safety Fast	October	2001	12
Rear Brake Drums Oil Leak VA	MG Service Information Sheet	August	1937	50
Rear Bumper Brackets (from body 593/5850) VA	MG Technical Information	01 February 1936		
Rear Bumper Fitting SA	MG Service Information Sheet	August	1936	38
Rear Bumper Strengthen VA	MG Technical Information	17 February 1938		VA 1073
Rear engine seal VA	SVW Review	Issue 19	2010	22
Rear Hub Ball Race Clamping VA	MG Service Information Sheet	Assume	1938	60
Rear Hub Bearings (T type)	Safety Fast	August	1992	27
Rear Hub Joint additional gasket (from axle No. 988) VA	MG Technical Information	30 August 1937		
Rear Lamps SA	SVW Review	Issue 7	1998	19
Rear Number Plate change (From body No. I400/6250 SA	MG Technical Information	05 January 1938		
Rear Number Plate change SA	MG Technical Information	04 November 1936		SA 0903
Rear Wheel Bearing Hub Wear - Shim to rectify SA	MG Technical Information	11 April 1938		
Rear Wheel Bearing Wear shim VA	MG Technical Information	11 April 1938		
Reboring - Safe Limits	Safety Fast	May	1991	36
Rebuild of a Charlesworth Part 1	SVW Review	December	1976	7
Rebuild of a Charlesworth Part 2	SVW Review	March	1978	11
Rebuild of a Charlesworth Part 3	SVW Review	March	1980	7
Rebuilding a VA Tourer	Safety Fast	June	1992	25
Reference Numbers for Spare Parts (Martin Brent)	SVW Newsletter	August	1967	n/a
Registering you Car with DVLA Issues	Safety Fast	February	2023	60
Registration Numbers reclaiming from DLVC	Safety Fast	January	1995	28
Regulator Box change SA	MG Technical Information	11 April 1938		SA 2487
Regulator Box change VA	MG Technical Information	11 April 1936		VA 1469
Regulators and Dynamos	SVW Review	Issue 23	2014	29
Reinbold and Christe bodied SVW's	SVW Review	Issue 31	2022	28
Replacing Wheel spokes	Safety Fast	March	2005	17
Representatives list	Safety Fast	February	1995	54
Restoring a SA Lessons learnt	SVW Review	Issue 11	2002	14
Retiming a VA Tickford	SVW Review	Issue 13	2004	7
Retrim VA Tourer	SVW Review	Issue 20	2011	41

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
Reverse Light Switch now Gearbox operated VA	MG Technical Information	11 April 1936		VA 1371
Rewiring - SA	SVW Review	Issue 9	2000	7
Rewiring - SA	SVW Review	Issue 9	2000	9
Rewiring an SA	Safety Fast	May	2008	81
Road Tax evidence in Europe (V8 Reg)	Safety Fast	April	2015	48
Road Test SA	SVW Review	Issue 8	1999	17
Road Test VA	Safety Fast	January	1984	29
Rocker Assembly (T Type)	Safety Fast	October	2014	18
Rocker Assembly and Oil Pressure	Safety Fast	March	2015	20
Rocker Cover - Oil Leakage	Safety Fast	November	2019	80
Rocking and Rolling Maintenance Tips	Safety Fast	March	2009	37
Rocking and Rolling Part 3	SVW Review	Issue 23	2014	8
Royal Windsor Heritage Festival 2009	SVW Review	Issue 18	2009	22
Rubber Engine mounting blocks (harder rubber) SA	MG Technical Information	15 June 1936		SA 0683
Running Board Replacement - VA	SVW Review	Issue 28	2019	14
Running Board Strips	SVW Review	Issue 9	2000	25
Running Board Support Replacement VA	SVW Bulletin	December	1968	4
Running In Original transfer on rev Counter	SVW Review	Issue 30	2021	8
SA - Fred Hale	Safety Fast	May	1981	4
SA - Kimbers 1936 Run	SVW Review	Issue 14	2005	20
SA One Family owned since new DFY34	MG Enthusiast	September	2014	36
SA - Schlumpf Motor Museum	Safety Fast	May	1979	4
SA & VA's in Competition	MG Enthusiast	March	1998	70
SA 0251 - The First SA	Safety Fast	September	2002	15
SA 0499 The Duchess	SVW Review	Issue 27	2018	41
SA 0507	SVW Review	Issue 14	2005	25
SA 0656 - CTU 807	SVW Review	Issue 32	2023	51
SA 0849 Saloon	Safety Fast	June	1993	23
SA 1425	MG Enthusiast	December	2022	80
SA 1787 Airy Coupe	SVW Review	Issue 33	2024	30
SA 1879 Lord Nuffield's car	SVW Review	Issue 27	2018	43
SA 1885 Special Tourer "Charlie"	SVW Review	Issue 30	2021	18
SA 1891 DPD 635	Safety Fast	March	1998	21
SA 1944 - MG 5435	Safety Fast	July	2023	29
SA 1961 at Pebble Beach	SVW Review	Issue 33	2024	31
SA 1965	SVW Review	Issue 33	2024	11
SA 2337 Christy	SVW Review	Issue 27	2018	39
SA 2387	SVW Review	Issue 14	2005	18
SA 2678 & 2859 - Bangers and Cash programme	SVW Review	Issue 31	2022	19
SA 2859 & 2678 - Bangers and Cash programme	SVW Review	Issue 31	2022	19
SA 2946 Racing Special	SVW Review	Issue 31	2022	32
SA 2983 Engine rebuild	SVW Review	Issue 22	2013	4
SA 893 (Ex David Washbourne) progress	Safety Fast	March	2017	47
SA 893 (Ex David Washbourne) Restoration Log	SVW Review	Issue 26	2017	13
SA 893 Saloon - Ex David Washbourne Car	Safety Fast	November	2023	82
SA 9119 - JB 0204	SVW Review	Issue 34	2025	46
SA Airy Coupe Road Trip - Malcolm Robertson	MG Enthusiast	December	2007	48
SA and the Wolseley 18/80, 18/85.	SVW Review	Issue 15	2006	9
SA Approved Extras 1939	SVW Review	Issue 6	1997	45
SA Back Axel Ratios	SVW Review	Issue 34	2025	53
SA Back Axle	Safety Fast	January	1991	21
SA Cars in Films	SVW Review	Issue 15	2006	18
SA Charlesworth Tourers	SVW Review	Issue 9	2000	5
SA Chassis (Picture)	Safety Fast	November	1998	17
SA Chassis Specification	Safety Fast	February	1986	21
SA Clutch replacement	SVW Review	Issue 21	2012	4
SA Colours	SVW Review	Issue 6	1997	44
SA Colours Modern Equivalents	SVW Review	Issue 6	1997	45
SA Comparison - Original and Restored cars	SVW Review	Issue 32	2023	37
SA Coupe Airy Special Body (Australia)	Safety Fast	September	2003	15
SA Detailed History	SVW Review	Issue 6	1997	40
SA Engine	Safety Fast	May	1987	22
SA Engine Rebuild	SVW Bulletin	June	1970	22
SA Essay	Safety Fast	April	1981	9
SA Gearbox Removal	SVW Newsletter	August	1983	n/a
SA Gearbox removal	Safety Fast	January	1991	19
SA Harry Hickling - African Safari	MG Enthusiast	January	2012	50
SA Harry Hickling Peking to Paris Rally	MG Enthusiast	February	2011	52
SA in Hollywood	SVW Review	Issue 27	2018	4
SA keeping cool	SVW Review	Issue 6	1997	29
SA Launch in 1935	SVW Review	Issue 31	2022	11
SA lessons learnt restoring a SA	SVW Review	Issue 11	2002	14
SA Lucas Part Numbers	SVW Review	Issue 6	1997	55
SA Nile Trial - Harry Hickling	MG Enthusiast	June	2009	32
SA Notes	SVW Bulletin	December	1968	3

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
SA on Tour 1936 Revisited in an MGB	Safety Fast	January	1999	15
SA on Tour in 1936	Safety Fast	October	1998	17
SA Original Cost	SVW Review	Issue 6	1997	42
SA Peking to Paris 2013	Safety Fast	September	2013	20
SA Performance	Safety Fast	March	2008	38
SA Production Changes	SVW Review	March	1978	16
SA profile	MG Enthusiast	February	1999	60
SA Progress report. Barry Witham	Safety Fast	March	1995	44
SA Prototype	Safety Fast	June	1984	35
SA Racing Car	MG Enthusiast	September	2012	76
SA Radio	Safety Fast	March	2001	21
SA Rear Lamps	SVW Review	Issue 7	1998	19
SA Restoration EMS 745	MG Enthusiast	December	2010	32
SA Resurrection	Safety Fast	December	1980	8
SA Rewiring	SVW Review	Issue 9	2000	7
SA Rewiring	SVW Review	Issue 9	2000	9
SA Road Test	SVW Review	Issue 8	1999	17
SA Saloon	Safety Fast	March	1965	39
SA Saloon - CYE 499	MG Enthusiast	September	1995	44
SA Saloon CTU 807	MG Enthusiast	March	2007	38
SA Saloon MG 4768 (David Washbourne)	MG Enthusiast	November	2004	38
SA Saloon Model	MG Enthusiast	October	1997	75
SA Saloon Profile	MG Enthusiast	November	2004	32
SA Saloon Purchase GPU 793	SVW Review	Issue 30	2021	31
SA Saloon Restoration - Barry Witham	MG Enthusiast	September	1995	46
SA Saloon Time warp	Safety Fast	March	1994	51
SA Seat Belts	Safety Fast	September	2009	38
SA Special	Safety Fast	January	1984	29
SA Special - Harry Hickling	SVW Review	Issue 16	2007	18
SA Special Body	Safety Fast	September	2009	39
SA Specials	SVW Review	December	1976	9
SA Specification	Safety Fast	October	1984	27
SA Tickford body Removal	SVW Newsletter	Annual	1971/72	5
SA Tourer	SVW Review	March	1980	18
SA Tourer by Coachcraft	Safety Fast	March	2004	16
SA Wet Clutch	MG Enthusiast	January	2023	76
SA with a Dickey Seat CBP 631	SVW Review	Issue 34	2025	5
SA1707	SVW Review	Issue 31	2022	39
SA1961	SVW Review	Issue 31	2022	43
Safe Limit for Reboring	MG Service Information Sheet	February	1938	52
Safety Fast Issues 1969-1992	Safety Fast	February	1993	18
Salmons & Sons - Tickford bodies	Safety Fast	October	2010	35
Salmons & Sons - Tickford Coachbuilders	Safety Fast	February	2007	8
SA's featured in Bangers and Cash	Safety Fast	March	2022	48
Scuttle Top Ventilator SA	MG Service Information Sheet	March	1938	53
Search for Holy Grill VA Part 1	Safety Fast	October	1992	21
Search for Holy Grill VA Part 2	Safety Fast	November	1992	20
Search for Holy Grill VA Part 3	Safety Fast	December	1992	22
Search for Holy Grill VA Part 4 (Notes)	SVW Review	Issue 9	2000	20
Search for Holy Grill VA Part 5	SVW Review	Issue 10	2001	16
Search for the Holy Grill (complete article)	SVW Review	Issue 6	1997	11
Seat Belt fitting to a VA Tourer	SVW Review	Issue 23	2014	16
Seat Belts - Children, The Law	Safety Fast	February	2010	80
Seat Leather Restoration (Magnetite)	Safety Fast	August	2020	15
Seating Dimensions	SVW Review	Issue 23	2014	48
Seats	Safety Fast	March	1985	36
Seats	SVW Review	Issue 18	2009	16
Security of your car	Safety Fast	September	1996	14
Selling your SVW	Safety Fast	March	2024	48
Service Piston Sizes	MG Service Information Sheet	March	1936	6
Service Sheets	Safety Fast	January	1978	20
Setting Ignition Timing	Safety Fast	November	2007	81
Shackle Pin Bush fitting to Spring Eye VA	MG Service Information Sheet	Assume	1938	58
Shackle Pin Bushes	Safety Fast	December	1991	53
Shackle Pins - VA	Safety Fast	January	1987	21
Shackle Pins change SA	MG Technical Information	13 February 1939		SA 2752
Shock Absorber Change VA	MG Technical Information	13 February 1939		VA 1915
Shock Absorber Conversion VA	SVW Review	Issue 22	2013	19
Shock Absorber Hand Control repositioned (from body 325/5614) VA	MG Technical Information	26 June 1937		
Shock Absorber Rebuild	Safety Fast	November	1996	24
Shock Absorber Ride Control Pump VA	MG Service Information Sheet	July	1938	54
Shock Absorbers	Safety Fast	October	1982	15
Shock Absorbers - Luvax	Safety Fast	December	1972	19
Shock Absorbers - Luvax	SVW Review	Issue 9	2000	27
Shock Absorbers - Telescopic	SVW Review	Issue 23	2014	8

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
Shock Absorbers (Telescopic Replacements)	SVW Review	Issue 17	2008	32
Shock Absorbers change to Telescopic	SVW Review	Issue 29	2020	16
Shock Absorbers changed SA	MG Technical Information	01 March 1937		SA 1424
Shock Absorbers changed to Piston Type SA	MG Technical Information	13 February 1939		SA 2752
Side Light Mounts	SVW Review	Issue 34	2025	34
Side Screens - VA	Safety Fast	November	1982	24
Silencer Flange SA	MG Service Information Sheet	September	1938	65
Silicon Brake Fluid	Safety Fast	March	1982	12
Silicon Brake Fluid	Safety Fast	October	1982	12
Silicon Brake Fluid	Safety Fast	January	1983	29
Silicon Brake Fluid - DOT 5	Safety Fast	November	1999	29
Silicon Fluid	Safety Fast	January	1991	21
Silicon Fluid	Safety Fast	May	1991	35
Silverstone 1998	Safety Fast	September	1998	48
Slow Running Return Spring change SA	MG Technical Information	17 February 1938		SA 2258
Slow Running Return Spring change VA	MG Technical Information	17 February 1938		VA 1078
Smiths / Jaeger Instruments	Safety Fast	March	2019	45
Smiths Jackall System	SVW Review	Issue 10	2001	24
So you want to buy an SVW	Safety Fast	January	2008	29
Social Media	SVW Review	Issue 28	2019	45
South Africa Members Update	SVW Review	Issue 29	2020	43
Spare Parts Reference Numbers (Martin Brent)	SVW Newsletter	August	1967	n/a
Spare Wheel Carrier change. VA	MG Technical Information	01 February 1938		VA 1162
Spark Plugs	MG Enthusiast	February	1992	22
Spark Plugs	Safety Fast	April	1995	25
Sparking Plug Gap	MG Service Information Sheet	February	1936	1
Special Bodies	Safety Fast	June	1983	31
Specials	Safety Fast	February	1994	34
Split pin removal	SVW Review	Issue 8	1999	24
Spot welds - Drilling Out	Safety Fast	November	1992	41
Spring Data	SVW Review	Issue 23	2014	12
Spring Shackles	SVW Review	Issue 23	2014	8
Springs - VA	SVW Review	Issue 26	2017	35
Standard extras	Safety Fast	September	1985	26
Starter Control SA	MG Service Information Sheet	July	1936	36
Starter Motor Switch - Fire Risk	Safety Fast	June	2010	83
Starting Dog and Handle change SA	MG Technical Information	01 May 1937		SA 1501
Statutory of the Road Notification (SORN)	Safety Fast	January	1998	10
Staying Safe (VA Safety Modifications)	SVW Review	Issue 34	2025	20
Steering	Safety Fast	December	1982	32
Steering and Suspension Wear	SVW Review	Issue 11	2002	21
Steering and Suspension Wear	Safety Fast	March	2009	38
Steering Angles	SVW Review	March	1980	26
Steering Angles	Safety Fast	May	1991	35
Steering Angles	MG Service Information Sheet	February	1948	61
Steering Arm Gaiters	SVW Review	Issue 31	2022	33
Steering Box	Safety Fast	September	1993	48
Steering Box Assembly	SVW Review	Issue 11	2002	22
Steering Box Assembly	Safety Fast	March	2009	38
Steering Box Bottom Cover (excludes VA 1276 and VA 1277) VA	MG Technical Information	11 April 1938		VA 1257
Steering Box Bottom end cover change SA	MG Technical Information	06 May 1938		SA 2559
Steering Box Improved Seal SA	MG Technical Information	01 February 1938		
Steering Box Leaks	SVW Review	Issue 31	2022	48
Steering Box Overall	Safety Fast	July	1998	52
Steering Box Overhaul and Improvement VA	SVW Review	Issue 25	2016	27
Steering Box Rebuild	SVW Review	Issue 23	2014	8
Steering Box Rebuild - VA	SVW Newsletter	Annual	1971/72	7
Steering Box Seal VA	MG Technical Information	01 February 1938		
Steering Column Control change VA	MG Technical Information	13 February 1939		VA 1965
Steering Column Repositioned (1 inch closer to centre) SA	MG Technical Information	05 January 1938		SA 2103
Steering Column rubber ferrule addition SA	MG Technical Information	25 May 1936		SA 0454
Steering Gear change SA	MG Technical Information	13 February 1939		SA 2753
Steering Gear Ratio change SA	MG Technical Information	15 June 1936		SA 0691
Steering Knuckle Adjustment SA	MG Service Information Sheet	February	1937	43
Steering Swivel Pin Thrust Arrangement VA	MG Service Information Sheet	September	1938	62
Steering Toe in	Safety Fast	March	1979	23
Steering Wander (In mini tips)	SVW Review	Issue 21	2012	17
Steering Wheel Bakelite centres	SVW Review	Issue 31	2022	47
Steering Wheel Change SA	MG Technical Information	04 November 1936		SA 0903
Steering Wheel change VA	MG Technical Information	13 February 1939		VA 1964
Stress (which bit is about to break?)	Safety Fast	December	2015	36
Stub Axles (T Type)	Safety Fast	June	1996	43
Stud (broken) Removal	Safety Fast	March	2021	66
Stud Extraction (MGA)	Safety Fast	July	2018	37
SU Carburettor Carburation	Safety Fast	January	2018	31

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
SU Carburettor Needles	MG Service Information Sheet	August	1939	7
SU Carburetors	Safety Fast	December	2002	11
SU Carburetors	Safety Fast	May	2002	32
SU Carburetors Tuning	MG Enthusiast	December	2006	68
SU Carburetors Tuning Part 1	MG Enthusiast	March	2006	68
SU Carburetors Tuning Part 2	MG Enthusiast	April	2006	68
SU Petrol Pump	Safety Fast	May	1994	28
SU Petrol Pump	Safety Fast	July	2007	64
Sump new VA	MG Technical Information	13 February 1939		TPBG 1790
Sump Removal VA	SVW Review	Issue 27	2018	24
Surviving SVW Cars Numbers	SVW Review	Issue 28	2019	5
SVW 2024 Event Netherlands Report	SVW Review	Issue 34	2025	24
SVW 60th Celebration	MG Enthusiast	September	1996	6
SVW Alpine Adventure	SVW Review	Issue 27	2018	12
SVW at the Royal Windsor Heritage Festival 2009	SVW Review	Issue 18	2009	22
SVW Car Totals	SVW Review	Issue 7	1998	6
SVW Cars 1938 Motor Show	SVW Review	Issue 9	2000	16
SVW cars Quick Check-Over Data Sheet	SVW Review	Issue 30	2021	26
SVW Chassis Information	Safety Fast	January	2001	27
SVW Cotswold Weekend	Safety Fast	November	1996	22
SVW Dashboards	SVW Review	Issue 22	2013	30
SVW Diamond Jubilee	Safety Fast	February	1995	8
SVW Event 2017 - Colchester	SVW Review	Issue 27	2018	29
SVW Event 2017 - Colchester	Safety Fast	September	2017	34
SVW Event 2023 - York	Safety Fast	September	2023	48
SVW Event 2025- Yorkshire	Safety Fast	September	2025	44
SVW Number of Surviving Cars	SVW Review	Issue 28	2019	5
SVW Pre 56 Rally New Zealand	MG Enthusiast	August	2010	46
SVW Production 1935 - 1939	SVW Review	Issue 12	2003	25
SVW Range History	SVW Review	Issue 28	2019	17
SVW Register 50th Anniversary	SVW Review	Issue 26	2017	4
SVW Register Awards - 2020	SVW Review	Issue 30	2021	21
SVW Register Early Days	SVW Review	December	1976	10
SVW Register Event 2019 - Alphen aan de Rijn	Safety Fast	September	2019	36
SVW Register Event 2021 - Lincolnshire	SVW Review	Issue 32	2023	25
SVW Register History	SVW Review	Issue 25	2016	4
SVW Services	MG Enthusiast	February	1994	50
SVW Sold in Holland	SVW Review	Issue 7	1998	22
SVW Weekend 1997 - Penbury, Kent	SVW Review	Issue 7	1998	8
SVW Weekend 2002 - Westphalia, Germany	SVW Review	Issue 12	2003	18
SVW Weekend 2003 - Kent	SVW Review	Issue 13	2004	13
SVW Weekend 2004 - Rhenen, Holland	SVW Review	Issue 14	2005	15
SVW Weekend 2005 - Norfolk	SVW Review	Issue 15	2006	14
SVW Weekend 2006 - Dorset	SVW Review	Issue 16	2007	15
SVW Weekend 2007 - Ironbridge	SVW Review	Issue 17	2008	17
SVW Weekend 2008 - Naarden, Holland	SVW Review	Issue 18	2009	19
SVW Weekend 2009 - Cambridge	SVW Review	Issue 19	2010	19
SVW Weekend 2010 - Munchengladback, Germany	SVW Review	Issue 20	2011	13
SVW Weekend 2011 Isle of White	SVW Review	Issue 21	2012	23
SVW Weekend 2012 - Yorkshire	SVW Review	Issue 22	2013	23
SVW Weekend 2013 - Beuzeville, France	SVW Review	Issue 23	2014	23
SVW Weekend 2014 - Oxfordshire	SVW Review	Issue 24	2015	23
SVW Weekend 2015 - Chichester	Safety Fast	September	2015	43
SVW Weekend 2018 - Bristol	Safety Fast	September	2018	38
SVW Weekend 2018 - Bristol	SVW Review	Issue 28	2019	27
SVW Weekend 29th to 31st August 2014	SVW Review	Issue 24	2015	23
SVW wreaked by Air Crash	SVW Review	Issue 27	2018	19
SVW's Art Deco Napier New Zealand	MG Enthusiast	November	2012	56
SVW's at MG90	Safety Fast	September	2014	42
SVW's at Ypres World War 1	SVW Review	Issue 23	2014	4
SVW's in Australia	SVW Review	Issue 26	2017	17
SVW's in Films - DXC 688, FYF 92	Safety Fast	March	2018	49
SVW's in Holland	Safety Fast	March	1998	19
Swiss Imports by JH Keller	Safety Fast	March	2008	36
Tappet Noise	Safety Fast	March	2015	39
Tax Disc - End Of	Safety Fast	October	2014	10
Tax Discs	MG Enthusiast	June	2015	86
Tax Discs - Replicas	Safety Fast	November	2017	81
Taxing your Car and SORN	Safety Fast	October	2007	16
Tecalamit Oiling System	SVW Bulletin	December	1968	9
Tecalemit change WA	MG Technical Information	25 May 1939		WA 0496
Television use of cars	Safety Fast	June	1992	24
The Duchess SA 0499	SVW Review	Issue 27	2018	41
The Sports Car Magazines 1935-1939	SVW Review	Issue 27	2018	50
Threads (Nuts & Bolts)	SVW Review	March	1978	17

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
Threads (Nuts & Bolts)	Safety Fast	October	1984	25
Throttle Controls SA	MG Service Information Sheet	June	1936	34
Throttle spindle coupling changed VA	MG Technical Information	17 February 1938		VA 0997
Tickford - Spare Wheel moved from back panel to LH wing SA	MG Technical Information	13 February 1939		SA 2782
Tickford body Removal SA	SVW Newsletter	Annual	1971/72	5
Tickford Coachbuilders - Salmons & Sons	Safety Fast	February	2007	8
Tickford Coachbuilders - Salmons & Sons	Safety Fast	March	2014	55
Tickford Hood Folding	Safety Fast	September	2024	59
Tickford Hood Restoration	SVW Review	Issue 33	2024	46
Timing Chain and Push Rod Replacements	SVW Review	Issue 29	2020	36
Toe in	Safety Fast	March	1979	23
Toe In	SVW Review	March	1980	26
Toe In	Safety Fast	May	1991	36
Tool Tray VA	SVW Review	Issue 8	1999	10
Tool Tray VA Saloon (Picture)	Safety Fast	May	1993	47
Toolbox catches (1)	Safety Fast	April	2017	85
Toolbox catches (2)	Safety Fast	May	2017	84
Torque Cables (Front Axle)	Safety Fast	May	1969	18
Torque Cables (Front Axle)	SVW Review	Issue 12	2003	21
Torque Cables (Front Axle)	Safety Fast	March	2009	39
Torque Cables Adjustment SA	MG Service Information Sheet	January	1937	41
Torque Settings (In mini tips)	SVW Review	Issue 21	2012	17
Tourer Spare Wheel security	Safety Fast	March	2014	39
Touring Comfort	SVW Review	Issue 20	2011	9
Touring in New Zealand - Pre 56 MG Rally 2023	SVW Review	Issue 32	2023	5
Touring in SA 1453	Safety Fast	August	1996	12
Touring Runs - Organising	Safety Fast	April	2015	16
Tracing the History of your SVW	SVW Review	Issue 6	1997	54
Tracing the History of your SVW	Safety Fast	March	2007	8
Track rod Ends - Changing	MG Enthusiast	April	2011	70
Tracker Security Devices	Safety Fast	April	2018	49
Travels and Rallying (VA Article)	Safety Fast	March	1995	43
Tribute to Prince Philip - (MG Heritage event 2009)	SVW Review	Issue 30	2021	5
Tuning the SU carburettor	MG Enthusiast	December	2006	68
Tuning the SU carburettor Part 1	MG Enthusiast	March	2006	68
Tuning the SU carburettor Part 2	MG Enthusiast	April	2006	68
Tyre and Wheel Safety	SVW Review	Issue 23	2014	47
Tyre sidewall markings	Safety Fast	August	2008	18
Tyre size variations	Safety Fast	August	2009	82
Tyre Wear and Wheel Balancing	Safety Fast	June	1999	15
Tyres	SVW Review	Issue 11	2002	20
Tyres	Safety Fast	March	2009	37
Tyres - ? Ban on 10 year old tyres	Safety Fast	April	2019	54
Tyres - How old ?	Safety Fast	May	2012	20
Tyres Checking & EU Regulations	Safety Fast	February	2013	21
Tyres Checking and effects of Ageing	Safety Fast	August	2024	52
Tyres Guide	MG Enthusiast	February	2013	72
University Motors	Safety Fast	February	1997	21
Unleaded Fuel	Safety Fast	April	1997	39
Unleaded Fuel	Safety Fast	January	2000	7
Unleaded Fuel in NZ	Safety Fast	January	2000	25
Unleaded Petrol	Safety Fast	January	1999	9
Unleaded Petrol	Safety Fast	January	1990	23
Unleaded Petrol	Safety Fast	July	1996	17
Unleaded Petrol	Safety Fast	June	1996	18
Unleaded Petrol (FWD)	Safety Fast	October	1998	31
Unleaded Use (MGB)	Safety Fast	April	1994	41
USA & Canada Members Update	SVW Review	Issue 29	2020	47
VA (Defence of)	Safety Fast	June	1977	7
VA - Export	Safety Fast	February	1977	14
VA - Foot Pedal Modification for Big Feet	SVW Review	Issue 28	2019	38
VA - New Springs	SVW Review	Issue 32	2023	13
VA - Racing	Safety Fast	October	1988	34
VA VerA (VA article)	Safety Fast	November	1968	31
VA & SA in war time Malta	SVW Review	Issue 27	2018	21
VA & Wolseley 12 Engine Differences	SVW Newsletter	August	1981	n/a
VA & Wolseley 12 Engine Differences	SVW Newsletter	May	1981	n/a
VA 0251	Safety Fast	May	1982	13
VA 0251	Safety Fast	May	1985	18
VA 0251 as at January 2023	Safety Fast	March	2023	49
VA 0251 The First VA	Safety Fast	March	2002	15
VA 0579	SVW Review	Issue 34	2025	13
VA 0764	SVW Review	Issue 20	2011	22
VA 0864	SVW Review	Issue 34	2025	38
VA 0864 Progress	Safety Fast	June	2025	82

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
VA 0885	SVW Review	Issue 13	2004	16
VA 0923 CDF 779 Barn Find	SVW Review	Issue 34	2025	9
VA 1355	Safety Fast	October	2025	82
VA 1385 Engine rebuild	SVW Review	Issue 27	2018	45
VA 1558	SVW Review	Issue 17	2008	28
VA 1693	Safety Fast	April	2025	82
VA 1756T	SVW Review	Issue 17	2008	15
VA 2022 - Full History	SVW Review	Issue 15	2006	28
VA 2269 Discovery FLT 565	Safety Fast	March	2025	42
VA 2299	SVW Review	Issue 33	2024	32
VA 2377	Safety Fast	October	2024	80
VA 2582	SVW Review	Issue 13	2004	18
VA 2582 (The Flying Saloon)	SVW Review	Issue 31	2022	17
VA 3398	SVW Review	Issue 33	2024	19
VA 3398	SVW Review	Issue 34	2025	16
VA at Montlhery	SVW Review	Issue 21	2012	32
VA Bearings Used	SVW Newsletter	February	1980	n/a
VA Brake Adjustment	SVW Review	Issue 27	2018	24
VA Brakes	Safety Fast	October	1993	43
VA Brakes 'C' Clips	SVW Review	Issue 8	1999	22
VA brakes modified to two leading shoes	SVW Review	Issue 22	2013	44
VA Chassis	Safety Fast	January	1991	20
VA Chassis Numbers	SVW Review	Issue 6	1997	49
VA Coupe BMW 770 (Black Beauties)	MG Enthusiast	March	2017	62
VA Coupe rebuild VA 0864S Elmar Gatilzi	Safety Fast	June	1994	31
VA Data Sheet	SVW Review	Issue 6	1997	66
VA Display Engine at Kimber House	SVW Review	Issue 24	2015	27
VA Engine Notes	SVW Review	Issue 9	2000	18
VA Engine Numbers	SVW Review	Issue 30	2021	15
VA Engine Rebuild - Police Specification	SVW Review	Issue 20	2011	12
VA Engine Rebuild - Police Specification (part 2)	SVW Review	Issue 21	2012	10
VA Engine removal	Safety Fast	September	1982	31
VA Engine removal	SVW Review	Issue 20	2011	35
VA featured in a Stained Glass Window	SVW Review	Issue 29	2020	42
VA Gearbox Rebuild	SVW Review	March	1978	19
VA General Update to Modern Standards	SVW Review	Issue 7	1998	3
VA Head Nuts tightening (In mini tips)	SVW Review	Issue 21	2012	17
VA Headlining Replacement	SVW Newsletter	Annual	1971/72	4
VA Hubs	SVW Review	Issue 6	1997	10
VA Ignition timing and Valve clearances	SVW Newsletter	December	1967	2
VA in The Family (GPJ 729)	SVW Review	December	1976	5
VA King Pin Replacement	SVW Review	Issue 28	2019	11
VA Lucas Part Numbers	SVW Review	Issue 10	2001	20
VA Memories	SVW Review	Issue 6	1997	35
VA Model	Safety Fast	March	2013	39
VA oil pick up problem	SVW Review	Issue 27	2018	23
VA Oil pressure Relief Valve	SVW Review	Issue 27	2018	49
VA Pedal modification (for wide feet)	Safety Fast	September	2013	42
VA Performance	Safety Fast	September	2002	15
VA Piston fitting	Safety Fast	May	2009	83
VA Police Cars	Safety Fast	April	1981	13
VA Police Cars	Safety Fast	July	1988	34
VA Police Cars	Safety Fast	October	1988	24
VA Police Cars	SVW Review	Issue 11	2002	11
VA Police Tourers - More details revealed.	SVW Review	Issue 26	2017	49
VA Praise	Safety Fast	March	1975	39
VA Production Changes	Safety Fast	April	2004	39
VA Prototype - DJO 804	MG Enthusiast	Summer	2021	34
VA Prototypes	Safety Fast	June	1994	33
VA rear engine seal	SVW Review	Issue 19	2010	22
VA Rebuild	Safety Fast	May	1984	19
VA Restoration RC 5411	MG Enthusiast	March	2018	46
VA Road Test	Safety Fast	January	1984	29
VA Rocker shafts	Safety Fast	March	2006	10
VA Rolling Road Experience	SVW Review	Issue 32	2023	35
VA Running Board Replacement	SVW Review	Issue 28	2019	14
VA Running Board Support Replacement	SVW Bulletin	December	1968	4
VA Safety Modifications	SVW Review	Issue 34	2025	20
VA Saloon - AMO 602 Road Test	MG Enthusiast	June	2008	42
VA Saloon - EYH 214	MG Enthusiast	November	2006	34
VA Saloon and Tourer (Keith Bush)	MG Enthusiast	March	2012	66
VA Saloon Autocar Run late thirties	SVW Review	Issue 6	1997	6
VA Saloon New Zealand Tour part 1	MG Enthusiast	January	2000	54
VA Saloon New Zealand Tour part 2	MG Enthusiast	February	2000	46
VA Shackle Pins	Safety Fast	January	1987	21

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
VA Shock Absorber Conversion	SVW Review	Issue 22	2013	19
VA Shooting Break	Safety Fast	March	2016	40
VA side screens	Safety Fast	November	1982	24
VA Specialloid Pistons	Safety Fast	October	1986	27
VA Springs	SVW Review	Issue 26	2017	35
VA Steering Box Rebuild	SVW Newsletter	Annual	1971/72	7
VA Sump Removal	SVW Review	Issue 27	2018	24
VA Tickford DTU 999	MG Enthusiast	January	2010	48
VA to Montlhery	MG Enthusiast	March	2012	60
VA Tool tray	Safety Fast	September	1987	30
VA Tool Tray	SVW Review	Issue 8	1999	10
VA Tourer AHS 87	MG Enthusiast	October	1995	51
VA Tourer BAP 689	MG Enthusiast	April	2021	28
VA Tourer Rebuild	Safety Fast	June	1992	25
VA Tourer Restored CVB 850	MG Enthusiast	March	2009	40
VA Tourer Retrim	SVW Review	Issue 20	2011	41
VA Wiring Diagram	SVW Review	Issue 27	2018	26
VA Woodie Saga	SVW Review	Issue 25	2016	17
VA0626	SVW Review	Issue 31	2022	42
VA0686	SVW Review	Issue 31	2022	37
VA1279 - DKW 506	SVW Review	Issue 31	2022	49
VA2139 - BMW 770	SVW Review	Issue 31	2022	13
VA2437 - CBL 192	SVW Review	Issue 31	2022	35
Valve Adjustment	Safety Fast	March	1992	45
Valve Adjustment VA	MG Service Information Sheet	July	1937	48
Valve Clearances	Safety Fast	July	1969	21
Valve Rocker Return Springs SA	MG Service Information Sheet	February	1937	42
Valve Spring Thickness change SA	MG Technical Information	01 May 1937		QPHG 1689
Valve Springs change to triple springs SA	MG Technical Information	01 February 1938		QPHG 2386
Vehicles of Historical Interest MOT Testing	Safety Fast	June	2018	10
Veneering Dashboard (MMM)	Safety Fast	October	2009	41
WA - EOY 672 - Goldie Gardner		October	2014	8
WA 0394 - MG 7068	SVW Review	Issue 32	2023	19
WA 0406 - Rebuild	SVW Review	Issue 20	2011	19
WA 0417 re-bodied with a Keller style body	SVW Review	Issue 21	2012	22
WA 0464	Safety Fast	July	2025	83
WA 0562	SVW Review	Issue 14	2005	9
WA 0585 Tickford History	SVW Review	Issue 30	2021	37
WA 251	Safety Fast	September	2001	15
WA Buying Guide	MG Enthusiast	April	2009	58
WA Description	Safety Fast	February	1982	29
WA Details an Differences	SVW Review	Issue 30	2021	47
WA Engine Lubrication (W.E. Blower 1950's)	SVW Review	Issue 25	2016	42
WA Engine Overhaul (Reprint from 1950's)	SVW Review	Issue 26	2017	45
WA Engine Work (Motor Magazine 1950's)	SVW Review	Issue 25	2016	40
WA History	Safety Fast	May	1986	25
WA Keller Replica - 680 UYG	MG Enthusiast	Spring	2019	52
WA Oil cooler problems	SVW Review	Issue 10	2001	7
WA Overdrive Installation	SVW Review	Issue 11	2002	9
WA Pistons & Bearings	Safety Fast	February	1986	22
WA Saloon	MG Enthusiast	February	2017	62
WA special Tickford body	SVW Review	Issue 23	2014	45
WA Special WA 0613	SVW Review	Issue 30	2021	11
WA Specification	Safety Fast	January	1990	24
WA Test Run - April 1939	SVW Review	Issue 21	2012	30
WA Tourer Profile	Safety Fast	June	2006	26
WA Wiring Diagram	SVW Review	Issue 29	2020	26
Water and Petrol Pumps	Safety Fast	August	1996	24
Water pump	Safety Fast	May	1970	22
Water Pump	Safety Fast	May	1984	19
Water Pump Changes (Internal) SA	MG Technical Information	01 May 1937		QPHG 1693
Water Pump cut away drawing	SVW Review	Issue 8	1999	25
Water Pumps interchangeability (In mini tips)	SVW Review	Issue 21	2012	17
Water System (Y Type)	Safety Fast	January	1995	32
Wedges for Front Axle Caster Angle	SVW Review	Issue 23	2014	8
Wet Clutch - SA	MG Enthusiast	January	2023	76
Wet Clutch History - Morris Morsels	SVW Review	Issue 32	2023	20
What to Take on a long journey	Safety Fast	March	2014	38
Wheel Balancing	SVW Review	Issue 11	2002	21
Wheel Balancing and Tyre Wear	Safety Fast	June	1999	15
Wheel Care	SVW Review	March	1978	14
Wheel Spokes - Replacement	Safety Fast	March	2005	17
Wheels	SVW Review	Issue 23	2014	8
Wheels - Centre lock	Safety Fast	January	1992	15
Wheels Spokes and Spinners	Safety Fast	March	2009	37

**SVW Articles up to Dec 2025**

ITEM	PUBLICATION	ISSUE/MONTH	YEAR	PAGE / From
Wheels, Spokes, and Spinners	SVW Review	Issue 11	2002	20
Where are they Now ?	SVW Review	Issue 13	2004	27
Windscreen Wiper Change (from body 851/8646) VA	MG Technical Information	13 February 1939		
Windscreen Wiper change SA	MG Technical Information	04 November 1936		SA 0903
Windscreen Wiper change SA	MG Technical Information	13 February 1939		SA 2752
Windscreen Wipers	Safety Fast	September	2007	37
Winter Checks	Safety Fast	December	1998	15
Wiper Control Switch Risk Elimination	Safety Fast	January	2021	66
Wire Wheel Maintenance	Safety Fast	March	2001	27
Wire Wheels	MG Enthusiast	August	2017	76
Wiring Diagram SA	SVW Review	Issue 28	2019	24
Wiring Diagram VA	SVW Review	Issue 27	2018	26
Wiring Diagram WA	SVW Review	Issue 29	2020	26
Wiring problems	Safety Fast	March	2006	11
Wiring System change SA	MG Technical Information	04 November 1936		SA 0903
Wolseley 12 Engine Differences	SVW Newsletter	August	1981	n/a
Wolseley 12 Engine Differences	SVW Newsletter	May	1981	n/a
Wolseley 18/80, 18/85 and the SA	SVW Review	Issue 15	2006	9
Wolseley/MG Gearbox	Safety Fast	January	1981	22
Wolseley/MG parts	Safety Fast	September	1980	8
Woodie Reconstruction	SVW Review	Issue 25	2016	17
Woodies	SVW Review	Issue 30	2021	35
World Wide Tour (A.Dakeyne, G.Page)	Safety Fast	November	1993	33
Your Car in Print	Safety Fast	April	2015	24
Ypres World War 1 SVW visit	SVW Review	Issue 23	2014	4